# Vehicle inspection report

### This vehicle has PASSED



### The AA has fully inspected this vehicle, covering:

- **Body exterior fittings**
- **Engine compartment**
- **Electrical controls**
- Interior and luggage compartment
- Front suspension, steering and under frame
- **Exhaust system**
- **Fuel system**

- Road test
- Interior fitting
- Rear suspension and under frame
- **Transmission and Final Drive**
- **Brakes**
- Wheels and tyres

Road tested for 10 miles on 12 November 2021

**Registration number** YB67BFY

By a certified AA vehicle inspector





### **Vehicle Inspection Report**

Dealer's Name: ARG Commercials Ltd

Inspection Number: BVI588320

Status: PASS

#### Key for points in the following sections:

P Pass
F Fail
A Advisory

N/A Not applicable

Please note: Right = Offside (O/S) and Left = Nearside (N/S) as viewed from the driver's seat.

#### **General Information:**

Registration: YB67BFY Mileage at start of inspection: 185811
Make: VOLKSWAGEN Colour: WHITE

Model: CRAFTER CR35 TDI BMT VIN WV1ZZZ2EZG6060843

Ramp Available: Yes Fuel Type Diesel

#### **Body Exterior Fittings:**

Bonnet Catch	P	Bonnet Hinges	P
Door Locks and Operation	P	Fuel Filler Cover/Flap	P
Panoramic Roof	N/A	Registration Plates	P
Sunroof/Convertible Operation	N/A	Windscreen and Glass	Р

#### **Interior Fittings:**

Air Vents and Operation

Mirrors	P	Roof Blind Condition and Operation	N/A
Seat Adjustment	P	Seatbelts	P
Engine Compartment:			
Abnormal Noises	P	Antifreeze Strength	P
Austilian Drive Dalta		Broke Fluid Level	

Boot/Tailgate Lock and Operation

**Auxiliary Drive Belts** Brake Fluid Level Clutch Fluid Level Coolant Cap N/A Coolant Leaks Coolant Level and Condition Engine Oil Level **Engine Mountings** Excessive Fumes/Smoke **Fuel Pipes** Hoses/Pipes Condition Idle Speed Power Steering Fluid Level Oil/Fluid Leak(s) N/A

Turbo/Supercharger Abnormal P

Noise/Leaks

#### **Electrical System and Controls:**

Air Condition Operation N/A Auto Stop Start Function P

Auxiliary Lights P 12V Battery visual condition P



## **Vehicle Inspection Report**

Brake Lights	Р	Controls/Switches	P
Fog Lights	P	Headlamp Washers	N/A
Headlights	P	Horn	P
Indicator/Hazard Lights	P	Instruments	P
Interior Lights	P	Number Plate Lights	P
Panel Lights	P	Reverse Lights	P
Side/Running Lights	Р	Start Button/Ignition Lock	P
Window Operation	P	Wipers and Washers	P
Front Suspension, Steering and Underb	ody:		
Anti-Roll Bar and Links	Р	Engine Underside Leakage	P
Power Steering Operation	P	Shock Absorbers Condition/Leaks	P
Springs/Suspension Units	P	Steering and Ball Joint	P
Steering Pipes/Hoses	P	Steering Rack Gaitors	P
Steering Rack/Box	P	Subframe Condition/Mountings	P
Suspension Arms/Bushes	P	Underbody Condition	P
Wheel Hubs/Bearings	P		
Rear Suspension and Underbody:			
Anti-Roll Bar and Links	P	Engine Underside Leakage	P
Shock Absorbers Condition/Leaks	P	Springs/Suspension Units	P
Subframe Condition/Mounting	P	Suspension Arms/Bushes	P
Underbody Condition	P	Wheel Hubs/Bearings	P
Transmission/Final Drive:			
Casings Condition	Р	Clutch Hydraulic System	Р
Clutch Operation	P	Driveshaft Assembly	P
Front CV Boots	Р	Gear Linkage Operation (wear)	Р
Mountings	Р	Oil/Fluid Leaks	Р
Propshaft	P	Propshaft Bearings/Supports	P
Rear CV Boots	P	Universal Joints	P
Abnormal Noises	P		
Exhaust:			
Catalytic Converter(s) Condition	N/A	Diesel Particulate Filter	Р
Heat Shields/Mountings	Р	Joints/Couplings	P
Manifold Condition	Р	Pipes Condition	Р
Silencer(s)	Р		
Fuel System:			
Breather Pipes	Р	Evidence of Leaks	Р
Fuel Lines	P	Tank	Р
Tank Fixings	P		
Drokes			

#### Brakes:



## **Vehicle Inspection Report**

P	Brake Pipes	P
Р	Flexible Hoses	Р
Р	Handbrake Operation	Р
P	Servo/Power Assistance	P
Р	Front Right Damage	Р
P	Rear Right Damage	Р
N/A	Locking Wheel Key Present	N/A
N/A	Auto Gearbox Park Function	N/A
N/A	Brakes (Vibration/Noise)	P
P	Engine Noise (Abnormal)	P
P	Exhaust Smoke	P
P	Hot Restarting	P
Р	Overheating Evidence	Р
N/A	Parking Sensors	Р
P	Steering Effort	Р
Р		
P		
Р		
P		
Р		
	P P P N/A N/A P P P N/A P P P P P P	P Flexible Hoses P Handbrake Operation P Servo/Power Assistance  P Front Right Damage P Rear Right Damage N/A Locking Wheel Key Present  N/A Auto Gearbox Park Function N/A Brakes (Vibration/Noise) P Engine Noise (Abnormal) P Exhaust Smoke P Hot Restarting P Overheating Evidence N/A Parking Sensors P Steering Effort P  P

YB67BFY



## **Vehicle Inspection Report**

#### Wheels & Tyres

Puncture onward travel: Spare

Position	Manufacturer	Tyre Width	Profile	Wheel Size	e Speed Rating	Wheel Type	Tread (mm)
Left Front	Other	235	65	16	R	Steel	5.8
Right Front	Other	235	65	16	R	Steel	4.9
Left Rear	Other	235	65	16	R	Steel	4
Right Rear	Other	235	65	16	R	Steel	4
Spare							

#### **Road Test**

Test distance: 10 miles Speed achieved up to: 60 mph

Dealer's Name ARG Commercials Ltd
Date 12 November 2021

Rect	Lifiaa	tion	Daa	uiro	<u>ا</u>
Reci	LITICa	ition	Rea	uire	a:

#### **Advisories**

AA YB67BFY

### **Vehicle Inspection Report**

#### **Advice and Information**

This report has been issued by Automobile Association Developments Limited ("AADL") as requested by the car dealer ("Dealer") referred to above. It is produced in accordance with the terms and conditions accepted by the Dealer and is provided for the sole use of the Dealer and should not be relied upon by any third parties.

An Engineer has carried out a visual inspection of the parts listed within the report, on the date specified above. Prior to carrying out the inspection, the Dealer and AADL entered into a contract for the AA Vehicle Inspection and the subsequent report which is subject to the AA Vehicle Inspection terms and conditions ("Terms"), a copy of which the Dealer acknowledges it has received and agreed to. The AA Vehicle Inspection does not cover the parts/items which are listed or referred to overleaf.

AADL will have no liability to anyone other than the Dealer in relation to the AA Vehicle Inspection carried out or the subsequent Report. The statutory rights of consumers are not affected.

The AA Vehicle Inspection can only describe and/or identify defects or advisories actually found and/or which are reasonably capable of being found upon an external visual inspection of the vehicle at the time of the check. We cannot be held and are not responsible for any latent defects which are later discovered.

The Engineer shall inform the Dealer of any defects and advisories detected as a result of the AA Vehicle Inspection. It is at the Dealer's sole discretion as to whether such defects and/or advisories are fixed by the time of sale. The Dealer remains liable for all defects and advisories reported.

#### Items/parts not checked by the Engineer are:

- a) Oil and fuel consumption;
- b) Source of oil leaks;
- c) Brake lining material (other than what is immediately visible and can be seen without dismantling anything);
- d) Brake fluid for contamination. Brake fluid will deteriorate over a period of time and We advise that it be replaced as recommended by the Vehicle manufacturer;
- e) Operation of cassette, compact-disc players, TV/DVD/satellite navigation systems,
- f) Bluetooth or other in-car entertainment;\*
- g) Sound or radio reception and alarm systems;\*
- h) Cylinder compression, vehicle electrics and electronics which would require specific diagnostic equipment;
- i) Exhaust emissions and/or catalytic converters. If this is assessed by the Inspector as passing the Inspection it only relates to confirming its external condition, gas tightness and security. The Inspector is unable to confirm its internal condition or effectiveness as this requires exhaust emission testing which is not included in the Inspection;
- j) The accuracy of in-car computer systems (for example, but in no way restricted to, computers used for route finding, fuel efficiency or otherwise);
- k) Exhaust emissions:
- I) Air conditioning functions and efficiency\*;
- m) The habitation area of Motorhomes The electrical systems and appliances, water fittings and appliances, and the gas fitting and appliances are not checked. These are beyond the scope of the Inspection. It is strongly advised that these are tested and checked by a suitably qualified person prior to purchase;
- n) Vehicle Technical Systems Many vehicles are fitted or equipped with automatic or computerised operating systems, which may be controlled by microprocessors. These include engine-management systems, fuel systems, ignition systems, air- conditioning systems, lambda-controlled systems, stereo radio, cassettes, amplifiers, compact discs (single and multi), TV/DVD, satellite navigation, active and self- levelling suspensions, gearboxes, turbo-chargers and superchargers, anti-lock braking systems, four-wheel drive and electronic lockable differential units, traction control, alarm and immobiliser systems, catalytic exhaust systems, and variable camshaft timing systems. Within the scope of the Inspection it is not possible to check fully the detailed operation of these systems due to the many variations in features and operating modes, and it is not possible to confirm that these systems are functioning fully to the manufacturers design specifications. As a result, the Inspector is unable to confirm the detailed operation of any of these systems other than giving an overall view and opinion on the performances generally inspected or checked. Therefore, We cannot be held in any way liable for failing to identify any malfunction or failure of any of these systems to perform to the specification as designed by the manufacturer; and
- o) Non-standard accessories as a result of personal modifications or otherwise.

<sup>\*</sup>These items will be turned on and off only and will not otherwise be checked.